

# Contact Mask Design Principles

Alissa M. Fitzgerald, Ph.D.

Principal, A.M. Fitzgerald & Associates

Stanford Nanofabrication Facility Open House

April 21, 2004



# Tutorial Outline

- Simple strategies for getting your masks right the first time, avoiding process headaches, and design for SNF-specific tools.
  - Understanding contact aligners and tool-specific issues
  - How process impacts mask design
  - Alignment marks and strategies
  - Mask layout tips and tricks
  - Design rules: the basics
  - Avoiding data file disasters



# SNF Exposure Tools



Name	Ultratech 1000	Karl Suss	EV 620	Nikon NSR
Type	1:1 Stepper	Contact	Contact/Prox	5:1 Stepper
Mask Size	3X5"	4" and 5"	5"	5"
Wafer Size	4" *	pieces-4"***	4"	4"
Maximum Exposure Area	sq. = 10 x 10 mm. rect = 21 x 7.2 mm	5" mask = 4" 4" mask = 3"	4" diameter	4"array
Obj. Separation	10- 21mm***	50-100mm		65mm
~ minimum resolution	1.25um lens rated****	1um	1um	.6um
Additional Features	Site-by-site stepper	Backside align	Anodic Bond,backside align	5:1 reduct.

## Exposure Information

- 6 inch manual loader is also available.
- \*\* 4 inch diameter is the maximum
- \*\*\* Aperture separation
- \*\*\*\* Down to 0.8um can be achieved in isolated circumstances.


## **EV620 Objective range**

- Top side objective travel range: **x direction 30 - 150mm separation** (8 - 150mm optional); **y direction +-75mm**; z direction +-5mm
- Bottom side objective travel range: **x direction 30 - 100mm separation** (8-100mm optional); **y direction +-12mm**, z direction +-5mm




# Contact aligners and tool-specific issues

- Max linewidth resolution
  - Don't design linewidths narrower than aligner capability!
- Max x-y tolerances
  - Best case layer-to-layer alignment tolerance (20X objectives, vacuum contact, skill)
    - ~ 0.6  $\mu\text{m}$  for top side
    - ~ 1  $\mu\text{m}$  front-to-back
  - Your designs should accommodate expected alignment error – based on your skill level and process (2  $\mu\text{m}$  is a safe number)



Karl Suss MA-6  
resolution




# Contact aligners and tool-specific issues

- Location of objectives
  - Range of motion is limited, so alignment marks must be in specific locations on mask

## EV620 Objective range

- Top side objective travel range: **x direction 30 - 150mm separation** (8 - 150mm optional); **y direction +75mm**; z direction +5mm
- Bottom side objective travel range: **x direction 30 - 100mm separation** (8-100mm optional); **y direction +-12mm**, z direction +5mm

- Objective field of view size
  - Determines how large to make alignment marks
- Unique tool features
  - Karl Suss vacuum lines, e.g.




**Karl Suss Chuck Vacuum lines**

drawing by Matt Hopcroft




# Mask writer features

- The fracturing grid: 0.5um for contact masks made at SNF
  - Mask writer takes in GDSII data, and ‘fractures’ or pixelates it
  - Fracturing grid determines ultimate resolution of the mask
  - Contract vendors can do 0.10 um, 0.25 um, but you pay dearly for resolution
- Maskwriter is designed to best handle ‘Manhattan geometry’
  - Squares, rectangles, 90 degree corners



# Mask writer features

- Polygons can be problematic
  - Circles, polygons, and slanted lines burden the conversion process because they are 'off-grid'
  - Large numbers of polygons will dramatically increase conversion time
    - At SNF, you may exceed mask writer capability
    - At commercial vendor, this will increase your mask cost
- Avoid polygons unless you really need them



# How process affects mask design





# Know your process before you start your mask


- Design your mask to fit your process and vice versa
  - Alignment to crystal axis (piezoresistors, anisotropic Si etch)
  - Lithography
    - Edge bead removal
    - Critical dimensions
  - Wet etch
    - Undercut compensation
  - DRIE etch
    - Center to edge variations in etch rate
    - Undercut compensation



# Alignment to crystal axis: crude alignment


- Some processes require alignment to crystal axis
  - Piezoresistors
  - TMAH/KOH etching
- For crude alignment to wafer flat:
  - Need alignment features in flat area of mask
  - Wafer flat is only within 2 degrees of true crystal axis

**Mask features  
near wafer flat**



# Alignment to crystal axis: precise alignment


- For precise alignment:
  - Need mask with an etch pattern
  - First process step: etch wafers in KOH/TMAH to reveal  $\langle 110 \rangle$  direction
  - Subsequent mask layers must have alignment marks that register with etch pattern



# Lithography considerations

- Edge bead removal (EBR) will remove outer 2 – 5 mm edge of resist
  - Any mask features in this area will be lost
  - Don't put alignment marks in this zone
- Don't pattern to edges of wafers
  - Tool holders
  - Etch non-uniformity
  - Device yield usually poor

EBR removes 2-5 mm




Don't put mask features here!




# Lithography considerations

- Disparate feature sizes will drive you crazy during processing
- For a given expose and develop time, or etch process:
  - By the time large features are developed, small features may be over-developed
- Options:
  - Split your designs into two separate mask sets
  - Compensate smaller features

**Mask**




**Reality**




# Wet etch considerations

- Undercut compensation needed for isotropic etch processes
  - Lateral loss is equal to etch depth
  - Compensate mask data to make sure you get what you want on the wafer
  - Some mask writers can automatically add “bias” – positive or negative




**Lateral undercut = etch depth**




# DRIE etch considerations

- Non-uniform etch rates
  - Wafer location
  - Feature size
  - Loading (open area/wafer area)
- Use it to your advantage!
  - Small features on wafer perimeter
  - Large features in wafer center



**Pattern area affects etch rate**





**Wafer location  
affects etch rate**



# DRIE etch considerations

- STS chuck exerts mechanical pressure on wafer
  - Designs must maintain mechanical integrity during etch
  - Avoid:
    - Scribe lines
    - Free die
    - Etch patterns to edge of wafer
    - High load layouts






# Mask Layout




# Mask layout: Before you start drawing

1. Outline your process
2. Prioritize your die list
3. Sketch global layout
  - Identify 'no-pattern' zones
  - Alignment mark areas
  - Test areas
4. Sketch die outlines, estimate die counts
5. Re-prioritize your die list
6. Then, start drawing your die patterns




# Alignment marks and strategies

- Alignment mark design
  - For contact aligners, whatever you like!  
(<http://snf.stanford.edu/Process/Masks/ContactAlignMks.html>)
  - Steppers have defined marks, see SNF website
- Sizing
  - Helpful to have one mark visible to naked eye
  - Smallest mark should be same size as Critical Dimension (CD)
- Labeling
  - Good idea for multiple layers
- Check your process: make sure a process step won't remove your marks!




# Alignment marks and strategies

- Layer to layer registration
  - All targets on one mask – convenient



- If Layers 1 and 2 must be well-aligned, have Layer 1 provide the target for Layer 2



# Drawing software


- Tanner L-edit Pro
  - Available at SNF on CAD room computers – free to lab users
  - Student version available for download (limited features)
- AutoCAD
- Coventorware
- DW2000
- Any software that can produce DXF, CIF, or GDSII format




# Drawing tips and tricks: Keeping your sanity

- The mask writer computer can easily manipulate your data:
  - Mirroring patterns (right vs. wrong reading)
  - Polarity change (clear vs. dark field)

**Dark field with many cutouts**



**Easier to draw the inverse and let the mask writer flip the polarity**



**Don't bend your brain  
drawing mirror images**



**Draw this instead**




# Drawing tips and tricks: Saving time

- (L-Edit) Instances and arrays: fast and accurate way to construct complicated patterns
  - Changes to cells propagate instantly up the hierarchy

Cell




Instance of cell  
arrayed into a  
row of 10



# Drawing tips and tricks: Saving time




- Don't waste time rounding corners or prettying rough edges unless they are  $> 10 \mu\text{m}$ 
  - Resist reflow will round sharp corners
  - Etch will smooth out patterns






# Drawing tips and tricks: Keeping your sanity

- Use round numbers: 5, 10, 50, etc.
  - Easy math for design by x,y coordinates
- Put the origin in a meaningful location




# Drawing tips and tricks: Nice details


- Label your die so you know what you're looking at through the microscope
  - Metal layer is best for labels
- Consistent bond pad pitch
- Align die patterns for easier dicing and testing



**5 saw cuts**




**10 saw cuts**





# Wafer Test Areas

- Special devices and patterns solely used to debug your process and your device
  - Etch completion
  - Layer thickness
  - Layer resistivity
  - Capacitance
  - Etc.
- Tight for space? Put test areas in the dicing lanes



# Drawing tips and tricks: Saving time

- Use layout templates
  - Beginners: borrow from your colleagues
  - Experts: create your own macros
  - L-edit: use setup files
- Develop your own design library
  - Use cells as much as possible
    - Easily copied to new design files
  - Use meaningful cell names



Any of these cells can be easily pasted to a new file



# Design Rules: the basics

- No linewidths or spacings  $< 2 \text{ um}$
- Stay on grid
- Avoid polygons as much as possible
- Dicing lanes =  $100 \text{ um}$
- Bondpads min size:  $200 \text{ um} \times 200 \text{ um}$
- Avoid feature size disparity
  
- Develop a design rule set that makes sense for your process and goals!
  - Parasitic capacitance
  - Positional tolerances
  - Undercut compensation
- Utilize automatic Design Rule Checks in CAD software



# Avoiding Common Data File Disasters\*


\*thanks to Paul Jerabek and Mahnaz Mansourpour for input



# Disaster #1: “Ack! Wrong polarity!!”

Symptom: Your mask is perfect, but it should have been clear (dark) field

- Confusion about whether to digitize data “Clear” or “Dark”



- Still confused? Ask Paul Jerabek, your mask vendor, or an experienced user to look over your data and request form



# Disaster #2: “This isn’t what I wanted”

Symptom: Your mask file looks fine, but the mask is wrong

- Commonly caused by conversion and fracturing problems:
  - Stay on grid
  - AutoCAD users: close all shapes and lines – indeterminate features will cause serious problems
  - Make sure each layer has a unique GDSII number
  - Less sophisticated GDSII converters will eliminate confusing or conflicting data
    - You won’t always get a warning in the log







# Disaster #3: Open circuits

Symptom: Occurrence of gaps in mask pattern

- When drawing shapes, overlap or “and” data areas to guarantee closed patterns



**Nice overlap**



**Open circuit**

- GDSII only allows square-ended wires
  - Rounded or beveled wires will be truncated to squares – this can create opens in your pattern



# Disaster #4: “Hmm, this doesn’t look right”


Symptom: Printed wafer looks perfect, but why do all the text labels look wrong?

- Draw your data as you intend it to look on the wafer
- “Reading” is defined as how the mask looks when **\*\*chrome side is up\*\***
  - Frontside masks are typically “Wrong” reading
  - Backside masks need to be “Right” reading


What’s in your data file:





Wrong reading:



Chrome side down,  
against wafer



Right reading:



# Disaster #5: “Why did it cost so much?!”

Symptom: Racing heartbeat upon receipt of bill

- Avoid polygons as much as possible
  - If you have a huge number of polygons, check with your mask vendor first
  - Get a vendor estimate on mask write time to avoid sticker shock
- Don’t “flatten” your data! (L-edit)
  - Flattening removes cell hierarchy
  - Data file becomes huge



# Final Notes

- Check your file (prior to GDSII conversion)
  - Have a colleague review your work
  - Sleep on it
  - Review design rules
- Check after GDSII conversion, too
  - Use a free GDSII viewer:  
[http://www.dolphin.fr/medal/socgds/socgds\\_free\\_overview.html](http://www.dolphin.fr/medal/socgds/socgds_free_overview.html)
  - Make sure everything is there!



# Need Help?

- A. M. Fitzgerald & Associates does end-to-end MEMS development, including photomask design
  - Knowledgeable about SNF exposure tools, as well as local commercial vendors
  - We use Tanner EDA L-edit
  - Custom L-edit templates
  - Custom test chip patterns
  - Macros
  - Get it done quickly and accurately!

